## **NEW SITE IDENTIFICATION**

Pa	t A - To Be Completed By Observer		
1.	Person Initiating Report: Jacob Harris	Phone: 526-1877	
	Contractor WAG Manager: Douglas Burns	Phone: 526-4324	_
2.	ite Title: 011, Debris West of the Southern End of Highway 22		
3.	Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.  There is debris located adjacent to an unmarked dirt road heading west approximately .9 miles north of the highway 22/33 intersection. Approximately .5 miles along this dirt road are two debris piles that contain rusted cans and wood. One site contains the remains of old car body panels. The GPS coordinates of the site are E324278.452 by N787615.356. The reference number for this site is 011and can be found on the summary map as provided.		
Pa	rt B – To Be Completed By Contractor WAG Manager		
4.	Recommendation:		
	<ul> <li>This site meets the requirements for an inactive waste sit FFA/CO Action Plan. Proposed Operable Unit assignme WAG: 10</li> <li>This site DOES NOT meet the requirements for an inactivincluded in the INEEL FFA/CO Action Plan.</li> </ul>	ent is recommended to be included in the Operable Unit: 10-08	FFA/CO.
5.	Basis for the recommendation:		
	The conditions that exist at this site indicate the potential for a or Disturbance of Suspected Inactive Waste Sites.	an inactive waste site according to Section	on 2 of MCP-3448 Reporting
6.	The basis for recommendation must include: (1) source desconcern; and (4) descriptions of interfaces with other program.  Contractor WAG Manager Certification: I have examined the believe the information to be true, accurate, and complete.	ns, as applicable (e.g., D&D, Facility Ope	rations, etc.)itted in this document and
Na	Tie: 12 Signature:	مراح کی ۔	Date: 5/15/00
ш.,,			

435.36 04/14/99 Rev. 03

## **NEW SITE IDENTIFICATION**

Part C – To Be Completed By INEEL FFACO/CO WAG Managers					
7. WAG Operable Unit:					
DOE WAG Manager Concurrence:	Concur with recommendation.	☐ Do not concur with the recommendation.			
Signature: Pott Krisupa					
Date: 5131100	-				
EPA EAP WAG Managers Concurrence:	Concur with recommendation.	☐ Do not concur with the recommendation.			
Signature: 2007 2005	•				
Date: 6/5/00	<del>-</del>				
State of Idaho WAG Managers Concurrence:	Concur with recommendation.	☐ Do not concur with the recommendation.			
Signature: Kerry Winter	-				
Date: 6-N4-00 Explanation follows:	-				
Explanation follows.		į			
Part D – To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)					
8. FFA/CO RPM's Concurrence:					
For DOE-ID					
Name: Kathleen Hain Signature: Xathleen	2 Ham Date: 7/12/00				
For EPA Region X					
Name: Wayne Pierre Signature: Nay 1	1666 Date: 71) 100	☐ Do not concur. Explanation follows:			
For State of Idaho					
Name: Dean Nygard Signature:	14900 Date: 6/23/00				



MISC-11, Debris West of the Southern End of Highway 22



MISC-11, Debris West of the Southern End of Highway 22



MISC-11, Debris West of the Southern End of Highway 22



MISC-11, Debris West of the Southern End of Highway 22



MISC-11, Debris West of the Southern End of Highway 22